

FIG. 1





FIG. 2


FIG. 3



FIG. 4**FIG. 5**

FIG. 6




FIG. 7




FIG. 8








FIG. 9

9/16

FIG. 10



10/16

FIG. 11




FIG. 12




FIG. 13





FIG. 14

(A)



(B)





FIG. 15**FIG. 16**

Case	1	2	3	4	5
S_{fc}	NOT DETECTED	NOT DETECTED	NOT DETECTED	DETECTED	DETECTED
S_{fL}	NO CHANGE IN LEVEL	DECLINES BY L_d (dB)	DECLINES BY ANY LEVEL	DECLINES BY L_d (dB)	DECLINES BY MORE THAN L_d (dB)
REFRIGERATOR	NORMAL	NORMAL	NORMAL	ABNORMAL	ABNORMAL
LOW-NOISE AMPLIFIER	NORMAL	ABNORMAL	ABNORMAL	NORMAL	ABNORMAL

FIG. 17







FIG. 18**FIG. 19**

FIG. 20**FIG. 21**